## Air Ionizer Verification Record

Ionizer Verification Sequence Number: 08 - 100 WORKING STANDARD USED Asset/ISO #: Manufacturer: Model: Serial No. Calibration Date: Calibration Due: Calibration By: 25171 TON 775 6779 2-20-08 8-20-09 JPL AIR IONIZER INFORMATION Asset/ISO #: Manufacturer: Verification By: Model: Verification Due: 22451 TON 8467 Fail: Y/N? 2-25-08 Cleaned: Y/N? 2-4-09 Location: Adjusted: Y/N? Prior Sequence# Minh De 08-011 VERIFICATION DATA (from Table 1) Fan controller setting: Low Distance of ionizer from the charge plate: Ionizer Float Potential Tolerance Vdc. Measured Float Potential values recorded below. Comments: 10 Vdc. 10 Ionizer Discharge Voltage Range: ± 1000 Vdc to < ± 50 Vdc (from Table 1) Ionizer Discharge Time Tolerance: 20 seconds. (from Table 1) Measured Discharge Time in second(s) and recorded values below. 2 (+1000 to +Vdc) 3 (+1000 to +Vdc) 4 (+1000 to +Vdc) 5 (+1000 to +Vdc) Comments: 4.9 sec 5.6 sec 5.3 sec 4.8 2 (-1000 to -Vdc) 3 (-1000 to -Vdc) 1 (-1000 to -Vdc) 4 (-1000 to -Vdc) 5 (-1000 to -Vdc) Comments: 5. 7 sec 6.1 5.6 sec 6.2 5.7 Record any corrective action required to restored ionizer operation (cleaning, adjustment, replacement, etc.) If Ionizer was replaced, indicate below the identification of replacement. Asset/ISO #: Manufacturer: Model: Serial No.: Sequence number for verification of replacement lonizer: Record inspection schedule and rational for that schedule.